







## Thiruvananthapuram, Kerala, India - 695034

(Established as University of Travancore by the Travancore University Act in1937 and reconstituted as University of Kerala by the Kerala University Act of 1957 and presently governed by the Kerala University Act of 1974 passed by the Kerala State Legislative Assembly)

(Re-accredited by NAAC with 'A' Grade)

AdBIV(CP).2020

## **QUOTATION NOTICE**

Competitive Quotations are invited from interested vendors inside Kerala for the supply of **one number of inverter** for use in the PVC's chamber of the University of Kerala as follows:

## **Conditions**

- 1. Total amount including all charges and taxes should be quoted.
- 2. GST % details should be mentioned( GST No of University: 32AAAJU0328F1ZJ)
- 3. Complaints with the items supplied should be rectified/ replaced to the satisfaction of the University by the suppliers at their own cost.
- 4. Payment will be made only after the supply of the items at our own site.
- 5. The undersigned reserves the right to reject /accept any quotation without assigning any reason.

The sealed quotations should be addressed to the undersigned superscribing as 'Quotations for the supply of **one number of inverter** for use in the Pro-Vice Chancellor's chamber of the University'. Last date of receipt of quotation is at **03.00 pm on 30.11.2020**. The quotations will be opened at 3.30 pm on the same day in presence of the vendors then present, following all COVID 19 restrictions imposed by the Government. Detailed specification is attached.

**REGISTRAR** 

Specification for inverter / UPS for use of PVC's chamber to connect electrical devices is given below,

- Branded 5KVA/4KW Inverter/ Offline UPS
- 2. Input Voltage 190-270V, 50Hz
- 3. Pure sinewave output, 230V 50Hz
- 4. Bypass facility, Overload protection, and display
- 5. CPRI/BIS or relevant certification (attach copy).
- 6. Inverter Warranty: Minimum two year
- 7. Tubular Battery of premium brand like Exide/ Amaron for 1 Hr Backup
- 8. Battery Rack
- 9. Battery Warranty: Minimum 4-year replacement