Schedule of Items

TW/MACE/6755/01/2018/CF

16.04.2017

Sealed quotations are invited from the Government approved workshops and authorised dealers of Ashok Leyland limited for the repair of the University Vehicle KL-01-BE-6755 for the following works

				Spare Part	LABOUR
Sr.No	ITEM	SPECIFICATION	Qty	Cost(Inc: Taxes)	(Inc: taxes
	M	ECHANICAL JOBS			
1	Water Service Vehicle Complete	Inclusive of interiors/ exterior	1 Job	NA	
	Carry out Greasing- Clutch Pedal, Brake Pedal, Relay shaft & Ball joints (Clutch Withdrawal), Clutch with drawal sleeve & liner, Center bearing Joint, Propeller shaft UJ Cross, Splines, Inter axle propeller shaft UJ Cross, Drag Link, Track rod and King pin	Gulf MP Grease Max NLGI1/Servo grease ALT	2 kg		
3	Remove and replace Engine Oil, Air Compressor Oil	Gulf Super Fleet LE Dura Max 15W-40	18.5 L		
4	Replace Gear Box oil	SAE 90	6.5 L		
5	Replace Differential Oil	SAE 140 EP	10 L		
	Remove and replace - Front and Rear Axle Hub greasing with all consumables	Gulf Crown Max RRS or Servo Gem ALT	4 Sets		
7	Remove and replace oil Filter	Full Flow Type - Ashok Leyland genuine	1 No		
8	Remove and replace AXLE PACKING	Ashok Leyland Genuine	4 Sets		

Sr.No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
9	Remove and replace THRUSH PAD HOUSING	Ashok Leyland Genuine	4 Sets		
10	Remove and replace THRUSH PAD WASHER	Ashok Leyland Genuine	4 Sets		
11	Replace Speed governor cable type with Direct Fuel Control type	THINTURE/AUTOGRADE/MER CYDA	1 Job	NA	
12	Remove and replace Fuel Strainer	Ashok Leyland Genuine	1 Set		
13	Remove and replace Air Filter	Ashok Leyland Genuine	1 No		
14	Remove and replace Power Steering fluid	Gulf Power Sttering DuraMAX /Servo Transdex II	4.5 L		
15	Reposition the pnuematic door switch from existing position to right hand side of driver, renew complete air pipe used for pnuema tic door operation handle. Re route the pipe avoiding engine area. Cover the entire length with heat insulating sleeve	Pipe 6mm - 10 m Pipe covering Sleeve - UL-90, UL-105C, and RoHS grade sleeve 10m			
16	Set right dents on body	As per RTO Norms	6 sq ft		
17	Check up and adjust full throttle operation	As per manufacturer recommended standards	1 Job	NA	
18	Check up and adjust stop cable	As per manufacturer recommended standards	1 Job	NA	
19	Blow clean all wheels and polish brake liners and adjust all brakes	As per manufacturer recommended standards	1 Job	NA	
20	Clean and adjust wheel bearings	As per manufacturer recommended standards	1 Job	NA	

Sr.No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
21	Check and top up gear box and differential oil level	As per manufacturer recommended standards	1 Job		
22	Check up UJ cross	As per manufacturer recommended standards	1 Job	NA	
23	Check up all spring bushes and shackles	As per manufacturer recommended standards	1 Job	NA	
24	Ajust all pedal and cable free plays	As per manufacturer recommended standards	1 Job	NA	
25	Top up king pin oil	As per manufacturer recommended standards	1 Job	NA	
26	Tighten all body bolts and platform bolts	As per manufacturer recommended standards	1 Job	NA	
27	Replace gear lever boot		1 Job		
28	Replace radiator cap, Arrest radiator leak		1 Job		
29	Check all lights, set right all lights to working condition	As per manufacturer recommended standards	1 Job		
30	Apply FRP/GRP and carry out patch work roughly	Approved quality	3Sqft		
31	Supplying Polyurethane (PU) paints - Golden Yellow inclusive of all consumables	DUPONT/3M/KANSAI NEROLAC/NIPPON/BERGER/ PPG	2 Liter		NA
32	Supplying Polyurethane (PU) paints - Brown inclusive of all consumables	DUPONT/3M/KANSAI NEROLAC/NIPPON/BERGER	1 Liter		NA
33	Under Body Paint - Black/Brown inclusive of all consumables	DUPONT/3M/KANSAI NEROLAC/NIPPON/BERGER	2 Liter		
34	Aluminium Enamel inclusive of all consumables	ASPA/PPG/NEROLAC/BERGE R	2 Liter		_

Sr.No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
35	Indicators - (Red Colour-3 Nos, Amber Colour-1 and White -1, Top light 2 Nos)	Any ARAI approved make	2 Pairs		
36	Number Plate light	Ashok Leyland Genuine	1 Set		
37	Art Work	As per RTO Norms	1 Job		
38	Remove and replace Passenger Cabin Light	ARAI Approved	3 Nos		
39	Fix window clamps	As per RTO Norms	15 No		
1 ДП	Replace driver side door glass beading	As per RTO Norms	1 job		
41	Replace Seat back rexin	As per RTO Norms	4 nos		
42	Replace seat rexin	As per RTO Norms	3 nos		
43	Set right clutch operation	As per manufacturer recommended standards	1 job		

Spare Part
Cost(Inc: Taxes)

LABOUR (Inc: taxes

Signature and seal of firm