Schedule of Items

TW/MACE/6755/01/2017/CF

06.03.2017

Sealed quotations are invited from the Government approved workshops and authorised dealers of Ashok Leyland limited for the repair of the University Vehicle KL-01-BE-6755 for the following works

Sr.N	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
		MECHANICAL JOBS			
1	Water Service Vehicle Complete	Inclusive of interiors/ exterior	1 Job	NA	
2	Remove and replace Engine Oil, Air Compressor Oil, FIP Oil	Gulf Super Fleet LE Dura Max 15W-40	18.5 L		
	Remove and replace - Front and Rear Axle Hub greasing with all consumables	Gulf Crown Max RRS or Servo Gem ALT	4 Sets		
4	Remove and refit fuel injectors	Ashok leyaland approved process			
5	Remove and refit FIP assembly	Ashok leyaland approved process			
6	Carry out injector cleaning and calibration	Ashok leyaland approved process	1 Job		
7	FIP calibration and overhaul	Ashok leyaland approved process	1 Job		
	Remove and replace Engine Oil Filter	Ashok Leyland Genuine	18.5 L		
9	Remove and replace Fuel Filter Cum Water Filter	Ashok Leyland Genuine	1Set		
10	Remove and replace Fuel Strainer	Ashok Leyland Genuine	1 Set		
11	Remove and replace Air Filter	Ashok Leyland Genuine	1 No		
12	Remove and replace Power Steering fluid	Gulf Power Sttering DuraMAX /Servo Transdex II	4.5 L		

Sr.N	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
13	Remove and replace oil Filter	Full Flow Type - Ashok Leyland genuine	1 No		
14		Ashok leyaland approved process			
15	Carry out Greasing- Clutch Pedal, Brake Pedal, Relay shaft & Ball joints (Clutch Withdrawal), Clutch with drawal sleeve & liner, Center bearing Joint, Propeller shaft UJ Cross, Splines, Inter axle propeller shaft UJ Cross, Drag Link, Track rod and King pin	Gulf MP Grease Max NLGI1/Servo grease ALT	2 kg		
16	Remove and replace AXLE PACKING	Ashok Leyland Genuine	4 Sets		
	Remove and replace THRUSH PAD HOUSING	Ashok Leyland Genuine	4 Sets		
	Remove and replace THRUSH PAD WASHER	Ashok Leyland Genuine	4 Sets		
19	Replace side Glass 48"X15" (Toughened Black Colour) 6 mm thickness	ARAI Approved	1 piece		
	Fix rear window & Side Glass using silicon paste	ARAI Approved	4 Pieces		
	Apply FRP/GRP and carry out patch work roughly	Approved quality	3Sqft		
22	Set right dents on body		6 sq ft		
23	Driver Door Window beading replacement	Approved quality	1J0b		

Sr.N	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
24	Check up and adjust full throttle operation	As per manufacturer recommended standards	1 Job	NA	
25	Check up and adjust stop cable	As per manufacturer recommended standards	1 Job	NA	
	Blow clean all wheels and polish brake liners and adjust all brakes	As per manufacturer recommended standards	1 Job	NA	
27	Clean and adjust wheel bearings	As per manufacturer recommended standards	1 Job	NA	
28	Check and top up gear box and differential oil level	As per manufacturer recommended standards	1 Job		
29	Check up UJ cross	As per manufacturer recommended standards	1 Job	NA	
30	Check up all spring bushes and shackles	As per manufacturer recommended standards	1 Job	NA	
	Ajust all pedal and cable free plays	As per manufacturer recommended standards	1 Job	NA	
32	Top up king pin oil	As per manufacturer recommended standards	1 Job	NA	
33	Tighten all body bolts and platform bolts	As per manufacturer recommended standards	1 Job	NA	
34	Check all lights, set right all lights to working condition	As per manufacturer recommended standards	1 Job		
35	Check and certify speed governor operation	As per RTO Norms	1 Job	NA	
		BODY JOBS			
36	Supplying Polyurethane (PU) paints - Golden Yellow inclusive of all consumables	DUPONT/3M/KANSAI NEROLAC/NIPPON/BERGER/ PPG	9 Liter		NA
37	Supplying Polyurethane (PU) paints - Brown inclusive of all consumables	DUPONT/3M/KANSAI NEROLAC/NIPPON/BERGER	1 Liter		NA
38	Under Body Paint - Black/Brown inclusive of all consumables	DUPONT/3M/KANSAI NEROLAC/NIPPON/BERGER	2 Liter		
39	Aluminium Enamel inclusive of all consumables	ASPA/PPG/NEROLAC/BERGE R	2 Liter		

Sr.N	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
40	Rear Indicators Round - (Red Colour-3 Nos, Amber Colour-1 and		_		
	White −1)	Any ARAI approved make	2 Pairs		
41	Front Head Light - 2 Piece Assemblies (Right Side	Ashok Leyland Genuine	1 Pair		
42	Number Plate light	Ashok Leyland Genuine	1 Set		
43	Art Work	As per RTO Norms	1 Job		
1 44	Remove and replace Passenger Cabin Light	ARAI Approved	3 Nos		
12	Replace Driver Fan 24 V	ARAI Approved	1 Nos		
13	Replace Fog Lamp	ARAI Approved	2 Nos		
16	Fix window clamps		15 No		

Total Cost in Rupees

Spare Part Cost(Inc: LABOUR Taxes) (Inc: taxes

Signature and seal of firm