		Quote						
	Schedule of Items							
TW/M	W/MACE/2627/01/2017/CF 01.06.2017							
Sealed quotations are invited from the Government approved workshops and authorised dealers/service centers of Ashok Leyland limited for the repair of the University Vehicle KL- 01-N-2627 for the following works								
Sr No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes			
		Mechanical Jobs	1					
1	Water Service Vehicle Complete	Inclusive of interiors/ exterior	1 Job	NA				
2	Replace and renew Engine Oil	Gulf Super Fleet LE Dura Max 15W-40	18.5 L					
3	Renew and replace Oil Filter	Full Flow Type - Ashok Leyland genuine	1 No					
4	Renew and replace fuel filter Cum Water Filter	Ashok Leyland Genuine	1Set					
5	Renew and replace Fuel Strainer	Ashok Leyland Genuine	1 Set					
6	Clean Air Filter and renew Air Filter oil	As per manufacturer recommended standards	1 No					
7	Renew and replace Steering Gear Box oil	Gulf Super fleet dura 90 EP	1.5 L					
8	Renew and replace Gear Box oil	Gulf Super fleet dura 90 EP	2.5 L					

Sr No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
9	Dismantle and renew - Front and Rear axles Hub with greasing and all consumables	Gulf Crown Max RRS or Servo Gem ALT	4 Sets		
10	Renew and replace AXLE PACKING	Ashok Leyland Genuine	4 Sets		
11	Set right driver door lock stopper operation by correcting base.	Ashok Leyland Genuine	4 Sets		
12	Renew and replace THRUST PAD WASHER	Ashok Leyland Genuine	4 Sets		
13	Check up and adjust full throttle operation	As per manufacturer recommended standards	1 Job	NA	
14	Check up and adjust stop cable.	As per manufacturer recommended standards	1 Job	NA	
15	Blow clean all wheels and polish brake liners and adjust all brakes.	As per manufacturer recommended standards	1 Job	NA	
16	Clean and adjust wheel bearings.	As per manufacturer recommended standards	1 Job	NA	
17	Check and top up differential oil level	As per manufacturer recommended standards	1 Job		

Sr No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
18	Check up UJ cross adjust if necessary	As per manufacturer recommended standards	1 Job		
19	Check up all spring bushes and shackles	As per manufacturer recommended standards	1 Job		
20	Ajust all pedal and cable free plays	As per manufacturer recommended standards	1 Job	NA	
21	Supplying Bottle Jack 20 Ton	TORIN/PRO LIFT/POWER BUILT/KENNEDY	1 No		NA
22	Supplying tyre lever 120cm	TAPARIA/KENNEDY/STANLEY/DEW ALT	1 No		NA
23	Supplying one way wheel spanner -33mm	TAPARIA/KENNEDY/STANLEY/DEW ALT	1 No		NA
24	Carry out lubrication with Grease and adjust free plays for following points:- Clutch Pedal, Brake Pedal, Relay shaft & Ball joints (Clutch Withdrawal), Clutch with drawal sleeve & liner, Center bearing Joint, Propeller shaft UJ Cross, Splines, Inter axle propeller shaft UJ Cross, Drag Link, Track rod and King pin, Water pump	Gulf MP Grease Max NLGI1/Servo grease ALT	2 kg		

Sr No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
25	Top up king pin oil	As per manufacturer recommended standards	1 Job		
26	Adjust all valve tappets, carry out tuning of engine	As per manufacturer recommended standards	1 Job		
27	Tie rod end play setting, Wheel alignment checking	As per manufacturer recommended standards	1 Job	NA	
28	Tighten all body bolts and platform bolts	As per manufacturer recommended standards	1 Job	NA	
29	Check all lights, set right all lights to working condition	As per manufacturer recommended standards	1 Job		
30	Check and certify speed governor operation after overhauling	As per RTO Norms	1 Job		
31	Set right working of all gauges in instrument cluster	Ashok Leyland Genuine	2 Nos		
32	Fit driver side fan 24 V DC	ARAI approved	1 Job		

Body Jobs						
Sr No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes	
33	Set right driver door lock stppoer operation by correcting base.	As per RTO Norms	1 Job			
34	Set right passenger door stopper by adjusting base mounting screws	As per RTO Norms	1 Job			
35	Make and fix guide rods for driver shutter	As per RTO Norms	1 Job			
36	Replace base plate of shutters Driver Side 2 nd Conductor Side 2 nd ,4 th ,8 th	As per RTO Norms	1 Job			
37	Replace front wing sheild glass	LAMINATED GLASS IS: 2553 standard	12.5sq Ft			
38	Replace front wind sheild and rear glass beadings	As per RTO Norms	27ft/8. 25 m			
39	Replace rear view mirrors	6"X16" Complete with brackets for mounting on body by replacing existing Mirrors (AIS 001 & AIS 002 compliant)	2 Nos			

Ouote

Sr No	ITEM	SPECIFICATION	Qty	Spare Part Cost(Inc: Taxes)	LABOUR (Inc: taxes
40	Supplying and renewing rexin on seat rest and back rest Back rest - 2 nd , 3 rd , 6 th & 10 th seats on right side ,2 nd ,4 th , 7 th & 10 th seats on left side Seat Rest - left side 10 th seat	Blue colour ARAI approved make 11sq meter	1 job		
41	Clear out cracks on vehicle surface with putty, sand the surface and touch and polish vehicle complete with allkyd paint, painting passenger platform, underbody and wheel disc	As per RTO Norms	1 Job	NA	
42	Supplying Alkyd base paint - Golden Yellow Colour inclusive of all consumables	ASIAN/NEROLAC/BERGER/PPG	2 Liters		NA
43	Under Body Paint - Black/Brown inclusive of all consumables	ASIAN/NEROLAC/BERGER/PPG	3 Liters		NA
44	Brown Enamel inclusive of all consumables	ASPA/PPG/NEROLAC/BERGER	3 Liters		NA
45	Art work and stickering of emergency numbers alone	As per RTO Norms	1 Job		
		Total Cost in R	5		
				Spare Part	

Spare PartCost(Inc:LABOUR (Inc:Taxes)taxes

Signature and seal of firm