

**QUOTATION NOTICE**

Sealed quotations are invited for Repair of Furniture/Rattening/Upholstery of chairs in the University Office and Departments as detailed below:

Items	Qty	Rate	Items	Qty	Rate
<b>WOODEN CHAIR</b>			15	Polishing	
1	Repair of chair by replacing legs including cost of wood	1 No:	<b>DINING TABLE</b>		
		2 No:	16	Replacing plywood top with new plywood mica (including cost of wood)	
		3 No:			
		4 No:			
2	Arm Rest	1 No:	17	Replacing Frame	
		2 No:	18	Replacing legs.	1 No:
3	Seat Frame	1 No:	19	Polishing	
		2 No:	<b>STEEL ALMIRAH</b>		
		3 No:	20	Replacement of lock	
		4 No:	21	Replacement of Drawer	
4	Polishing	1 No:	22	Replacement of Rack	
<b>WOODEN TABLE</b>			23	Replacement of Stand	
5	Repairing table by replacing legs including cost of wood	1 No:	24	Replacement of door handle	
		2 No:	25	Painting of Almirah	
		3 No:	26	Replacement of Doors	
		4 No:	<b>STEEL CHAIR</b>		
6	Top		27	Replacement of Hand rest	
7	Frame		28	Fabrication of Hand rest and replacement	
8	Drawer				
9	Repair of lock		29	Joining broken frame by welding	
10	Polishing				
<b>COT</b>			30	Fabrication of new seat frame in wood	
11	Repairing cot by replacing plywood top		31	Fabrication of new back rest frame in wood	
12	Repairing cot by replacing side frame		32	Painting of Chair	
13	Repairing cot by replacing legs		33	Writing board	
14	Replacing lengthwise plank of the cot		34	Replacement of legs	

35	Replacement of bush,screw etc			<b>RATTENING OF CHAIRS(INCLUDING COST OF MATERIAL)</b>		
<b>STEEL TABLE</b>				<b>WOODEN CHAIR</b>		
36	Replacement of drawer		52	Seat and Back		
37	Replacement of Table top		53	Seat only		
38	Fabrication of mica abraded table top		54	Back only		
				<b>STEEL CHAIR</b>		
39	Replacement of Lock		55	Seat and back		
40	Painting of Table		56	Seat only		
41	Replacement of Cupboard door and fitting of frabricated door		57	Back only		
42	Repair of frame and replacement of one leg with new one		<b>UPHOLSTERY OF CHAIRS(INCLUDING COST OF MATERIAL)</b>			
<b>STEEL RACK</b>				<b>SEAT</b>		
43	Repairing of rack by strengthening the rack body			Frame size 40*25 mm Water and termite resistant plywood 12 mm Foam rubber cushion 50mm Rexin cover 1mm		
44	Replacement of nut and bolt			<b>BACK REST</b>		
45	Repainting of one rack			Frame size 40*25 mm Water and termite resistant plywood 6 mm Foam rubber cushion 25mm Rexin cover 1mm		
46	Replacement of one rack,partition and fitting of new one					
<b>ALMIRAH</b>						
47	Replacement of Lock					
48	Drawer					
49	Stand					
50	Door Handle					
51	Painting					

**Sd/-  
REGISTRAR**